

Oil Field Environmental Incident Summary

Incident: 20151030100853 **Date/Time of Notice:** 10/30/2015 10:08

Responsible Party: SAMSON RESOURCES COMPANY

Well Operator: SAMSON RESOURCES COMPANY

Well Name: RANCHERO 1819-8H

Field Name: AMBROSE

Well File #: 30349

Date Incident: 10/29/2015 **Time Incident:** 19:15

Facility ID Number:

County: DIVIDE

Twp: 163

Rng: 98

Sec: 18

Qtr:

Location Description: well pad

Submitted By: Brad Rogers

Received By:

Contact Person: Jeff Proberts
370 17TH ST. SUITE 2900
DENVER, CO 80202-5612

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	10	Barrels	8	Barrels		

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

No immediate risks associated with release

Areal Extent:

Potential Environmental Impacts:

No impacts. Oil stayed on well pad.

Action Taken or Planned:

The well was shut-in. The broken nipple was isolated and replaced with a solid bull plug. The oil on the pad was sucked up and residual oil was collected using environmental pads. Impacted soils were scrapped up and will be disposed of at approved landfill.

Wastes Disposal Location: Secure 13-mile Landfill

Agencies Involved:

Updates

Date: 10/30/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a valve/piping connection leak, remained on location according to the report. NDIC retains oversight.